

Internal Rotary Inspection System (IRIS) Ultrasonic Inspections of Heat Exchanger Tubes

IRISNDT uses IRIS to detect general corrosion/erosion and localized volumetric defects such as pitting, fretting, and others in ferrous (carbon steel tubes such as SA214 and SA179 tubes) and non-ferrous (stainless steel) tubes. IRIS measures tube wall thickness values based on ultrasound pulse echo techniques.

INSPECTION PREPARATION

Thorough internal tube cleaning is essential to obtain clear reliable results. The technique needs water as a couplant.

ADVANTAGES

- IRIS measures the absolute wall thickness value, as well as the internal and external diameters of the tube.
- Is accurate to +/- 0.005"
- Can be used for ferrous and non-ferrous tubes.
- Is excellent for identifying support wear.

LIMITATIONS

- This technique cannot detect cracking.
- Internal cleaning must allow access to heavy scale and debris free surfaces.
- Compared to techniques such as eddy current, the scan speed is slower. The pulling speed; 2 in/s.



Support has cut into tubes. Flaw identified with IRIS.

REPORTS

All indication calls detail the severity of the flaw(s), its (their) location in the tube, and if it is (they are) ID/OD initiated. This information is built to scale in an accurate 3D rendering of the exchanger.



General ID corrosion identified with IRIS. The IRIS indications are shown to the right.

% MultiView 6.0R7Q15 - [disk]					_ 0 🛛
ile View Mode Setup Operation Layout Special Help					
US IRIS Utrasound Encoders 🛛 🚳 👘 🖙 🖈 🖈 🔜 📾 🔁 🖸 🖬 📾 👁 🕾 💯 🔍 🔊 🔊 🐤 + 🐥 🚿 🔂		3 🗧			
Setup Inspect Analysis C.Scan - V/T - X: 53:167 in. dX: 51:534 in. Y: 100.976 * dY: 100.976 *	Cursor cu	£ WT: 0.000 in	. ID: 1.296 in.	OD: 0.000 in.	
	D				
E/2009 ProjectVData/					F
File A					
* 001003					
* 001004 * 001005	<u> </u>		-	_ 20	·
 002001 002002 					
* 002003					-
* 00204 * 00205					
* 002006					÷
* 003001					
Start Next					
					5
Internal offset 0 <u>+</u> 2					
Cursor cut WT: 0.135 in. ID: 1.111 in. OD: 1.380 in.	Statistics				
		WT	WL (%)		
	4	0.065	52	Report entry	
	-	0.260	0	Report entry	
		wr	ID	OD	
	Min.	0.046	0.162	0.393	
	Max.	0.193	2.741	1.909	
	Avg. Nomin.	0.100	1.246	1.447	
		2.1.04			

5311 86th Street NW, Edmonton, Alberta T6E 5T8 Phone: (780) 437-2022 Fax: (780) 436-4873

Calgary Lloydminster Barrhead Nisku

40 inster (78 ad (78 (78

(403) 279-6121 (780) 875-6455 (780) 674-3018 (780) 955-7616 Cold Lake Fort McMurray Red Deer (780) 826-6105 (780) 743-1536 (403) 347-1742

 Engineering, Calgary
 (403) 217-9684


 Engineering, Edmonton
 (780) 437-2022

 Rope Access Services
 (780) 437-2022





Internal Rotary Inspection System (IRIS) Ultrasonic Inspections of Heat Exchanger Tubes

Below are different images obtained while examining for ID pits in finfans and heat exchangers



62% ID Pit





5311 86th Street NW, Edmonton, Alberta T6E 5T8 Phone: (780) 437-2022 Fax: (780) 436-4873

Calgary Lloydminster Barrhead Nisku (403) 279-6121 (780) 875-6455 (780) 674-3018 (780) 955-7616 Cold Lake Fort McMurray Red Deer

(780) 826-6105 (780) 743-1536 (403) 347-1742

 Engineering, Calgary
 (403) 217-9684

 Engineering, Edmonton
 (780) 437-2022

 Rope Access Services
 (780) 437-2022

www.irisndt.com

Offices also located in the USA and UK